# Electrospark Deposition for U.S. Navy Component Repair Applications

January 2006 HCAT Meeting San Diego, CA

**Denise M. Aylor** 

**NSWC Carderock Division** 

West Bethesda, MD

Email: denise.aylor@navy.mil



maintaining the data needed, and c including suggestions for reducing	lection of information is estimated to completing and reviewing the collect this burden, to Washington Headqu uld be aware that notwithstanding ar DMB control number.	ion of information. Send comments arters Services, Directorate for Infor	regarding this burden estimate of mation Operations and Reports	or any other aspect of the 1215 Jefferson Davis	nis collection of information, Highway, Suite 1204, Arlington	
1. REPORT DATE  JAN 2006	2 DEDONT TYPE			3. DATES COVERED <b>00-00-2006 to 00-00-2006</b>		
4. TITLE AND SUBTITLE		5a. CONTRACT NUMBER				
Electrospark Deposition for U.S. Navy Component Repair Applica				5b. GRANT NUMBER		
				5c. PROGRAM ELEMENT NUMBER		
6. AUTHOR(S)				5d. PROJECT NUMBER		
				5e. TASK NUMBER		
				5f. WORK UNIT NUMBER		
				8. PERFORMING ORGANIZATION REPORT NUMBER		
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)				10. SPONSOR/MONITOR'S ACRONYM(S)		
				11. SPONSOR/MONITOR'S REPORT NUMBER(S)		
12. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution unlimited						
13. SUPPLEMENTARY NOTES  26th Replacement of Hard Chrome and Cadmium Plating Program Review Meeting, January 24-26, 2006, San Diego, CA. Sponsored by SERDP/ESTCP.						
14. ABSTRACT						
15. SUBJECT TERMS						
16. SECURITY CLASSIFIC	17. LIMITATION OF	18. NUMBER	19a. NAME OF			
a. REPORT unclassified	b. ABSTRACT unclassified	c. THIS PAGE unclassified	Same as Report (SAR)	OF PAGES 22	RESPONSIBLE PERSON	

**Report Documentation Page** 

Form Approved OMB No. 0704-0188

### Targeted Applications

- Steering & Diving Control Rods
- Hull Valve Stems
- Alloy 625 Seawater Components



### Control Rods and Seawater Hull Valve Stems

#### ISSUE

Unacceptable corrosion/wear of Alloy K500 control rods and valve stems

#### SOLUTION

Electrospark deposition of Alloy 400 to re-establish original dimensions



#### Hull Valve Stem





### Steering and Diving Control Rod





### Steering and Diving Control Rod









CARDEROCK

Defect Measured 0.016" to 0.021" in Depth



#### ESD Control Rod Repair

Before Repair



Defect Measured 0.012" to 0.017" in Depth





After Repair

#### ESD Control Rod Repair

Before Repair









After Repair

#### ESD Control Rod Repair

Before Repair




Defect Measured 0.003" to 0.013" in Depth






After Repair

### **ESD Repair Section #4**





### ESD Repair Sections After 127 Days in Seawater








CARDEROCK



### Blunt Chisel Defects ESD Repaired with Alloy 400



400um


Defect #1



400um

Defect #2

## Blunt Chisel Defects Rounded Out with Dremel Tool ESD Repaired with Alloy 400



Defect #2

### ESD Control Rod Demonstration Repair Status

- Identified voids and microcracks within narrow groove repair area and corrosion after seawater immersion
- Simulated defect study identified improvements in ESD repair with less severe defect geometry
- Additional research need to identify NDE methods to assure optimum repair quality



### Crevice Corrosion Repair of Alloy 625 Components

- Develop NSWCCD Capability to Deposit Crevice Corrosion Resistant Ni-Cr-Mo Alloys on 625 Substrates
  - Alloy C276
  - Alloy 59
  - Alloy 686




### ESD of Ni-Cr-Mo Alloys on Alloy 625 Crevice Corrosion Testing

- ESD Coatings of Alloy 686, C276, and 59
   Applied on Alloy 625 Panels
- Control Specimens Include Uncoated Alloy 686, C276, 59, and 625
- Triplicate Specimens Exposed per Condition for 180 and 365 Days in Filtered, Natural Seawater Immersion





### **ESD of Ni-Cr-Mo Alloys on Alloy 625**Crevice Corrosion Testing in Natural Seawater





#### ESD of Ni-Cr-Mo Alloys on Alloy 625





### Crevice Corrosion Testing of ESD Ni-Cr-Mo Alloys on 625





### Crevice Corrosion Test Results After 365 Days in Seawater

- ESD Alloy C276 Coated Specimens Showed Crevice Susceptibility at Crevice Sites
- Corrosion initiated between 9 and 14 days' immersion
- Maximum depth of attack = 0.005 in. (0.13 mm)
- ESD Alloys 686 and 59 on 625 & Wrought Control Specimens of Alloys 625, 59, 686, and C276 Remained Corrosion Resistant After 365 Days



#### ESD Alloy C276 Coated Specimens After 180 Days in Natural Seawater





Maximum Depth of Attack = 0.005 in. (0.13 mm)
Initiated After 9-14 Days' Immersion